

# POLPUR™

tables with recommended conditions of POLPUR™ tools

MH, MJ lathe	revolutions [r.p.m.]																								
	100	150	200	250	300	350	400	450	500	550	600	650	700	750	800	850	900	950	1000	1050	1100	1150	1200	1250	1300
100	1	1	1	1	1	2	2	2	3	3	3	3	4	4	4	4	5	5	5	5	5	6	6	6	7
150	1	1	2	2	2	3	3	4	4	5	5	5	5	6	6	7	7	7	7	8	8	9	9	10	10
200	1	2	2	3	3	4	4	5	5	6	6	7	7	8	8	9	9	10	10	11	11	12	12	13	14
250	1	2	3	3	4	4	5	5	6	7	7	8	9	9	10	11	11	12	12	13	14	14	15	16	17
300	2	2	3	4	4	5	5	6	7	8	8	9	10	10	11	12	12	13	13	14	14	15	16	17	18
350	2	3	4	4	5	5	6	7	8	9	9	10	11	11	12	13	13	14	15	15	16	17	18	19	20
400	2	3	4	5	5	6	7	8	9	10	10	11	12	12	13	14	14	15	16	16	17	18	19	20	21
450	2	4	5	5	6	7	8	9	10	11	11	12	13	13	14	15	15	16	17	17	18	19	20	21	22
500	3	4	5	7	8	9	10	11	12	13	14	15	16	16	17	18	18	19	20	20	21	22	23	24	25
600	3	5	6	8	9	11	13	14	16	17	18	19	20	21	22	22	23	24	24	25	26	27	28	29	30
700	4	5	7	9	11	13	15	16	18	19	20	22	24	26	27	28	28	30	30	31	31	33	35	36	38

MH, MJ horizontal	revolutions [r.p.m.]																								
	100	150	200	250	300	350	400	450	500	550	600	650	700	750	800	850	900	950	1000	1050	1100	1150	1200	1250	1300
100	1	1	1	1	2	2	2	2	3	3	3	3	4	4	4	4	5	5	5	5	5	6	6	7	7
150	1	1	2	2	2	3	3	4	4	4	5	5	5	6	6	7	7	7	7	8	8	9	9	10	10
200	1	2	2	3	3	4	4	5	5	6	6	7	7	8	8	9	9	10	10	11	11	12	12	13	14
250	1	2	3	3	4	4	5	5	6	7	7	8	9	9	10	11	11	12	12	13	14	14	15	16	17
300	2	2	3	4	4	5	5	6	7	8	8	9	10	10	11	12	12	13	13	14	14	15	16	17	18
350	2	3	4	4	5	5	6	7	8	9	9	10	11	11	12	13	13	14	15	15	16	17	18	19	20
400	2	3	4	5	5	6	7	8	9	10	10	11	12	12	13	14	14	15	16	16	17	18	19	20	21
450	2	4	5	5	6	7	8	9	10	11	11	12	13	13	14	15	15	16	17	17	18	19	20	21	22
500	3	4	5	7	8	9	10	11	12	13	14	15	16	16	17	18	18	19	20	20	21	22	23	24	25
600	3	5	6	8	9	11	13	14	16	17	18	19	20	21	22	22	23	24	24	25	26	27	28	29	30
700	4	5	7	9	11	13	15	16	18	19	20	22	24	26	27	28	28	30	30	31	31	33	35	36	38