

POLPUR™

tables with recommended conditions of POLPUR™ tools

LAPI T lathe m.	LAPI T																								
	100	150	200	250	300	350	400	450	500	550	600	650	700	750	800	850	900	950	1000	1050	1100	1150	1200	1250	1300
100	1	1	1	1	2	2	2	2	3	3	3	3	4	4	4	4	5	5	5	5	6	6	6	7	7
150	1	1	2	2	2	3	3	4	4	5	5	5	5	6	6	7	7	7	8	8	9	9	9	10	10
200	1	2	2	3	3	4	4	5	5	6	6	7	7	8	8	9	9	10	10	11	11	12	13	14	
250	1	2	3	3	4	5	5	6	7	7	8	9	9	10	10	11	12	12	13	13	14	14	15	16	
300	2	2	3	4	5	5	6	7	8	9	9	10	11	12	13	13	14	15	16	16	17	18	19	20	
350	2	3	4	5	5	6	7	8	9	10	11	12	13	14	15	16	16	17	18	19	20	21	22	23	
400	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
450	2	4	5	6	7	8	9	10	11	12	13	14	15	16	18	19	20	21	22	24	25	26	27	28	
500	3	4	5	7	8	9	10	12	13	14	16	17	18	20	21	22	24	25	26	27	29	30	31	33	
600	3	5	6	8	9	11	13	14	16	17	19	20	22	24	25	27	28	30	31	33	35	36	38	39	
700	4	5	7	9	11	13	15	16	18	20	22	24	26	27	29	31	33	35	37	38	40	42	44	46	

LAPI SP horizontal	LAPI SP																								
	100	150	200	250	300	350	400	450	500	550	600	650	700	750	800	850	900	950	1000	1050	1100	1150	1200	1250	1300
100	1	1	1	1	2	2	2	2	3	3	3	3	4	4	4	4	5	5	5	5	6	6	6	7	7
150	1	1	2	2	2	3	3	4	4	5	5	5	5	6	6	7	7	7	8	8	9	9	9	10	10
200	1	2	2	3	3	4	4	5	5	6	6	7	7	8	8	9	9	10	10	11	11	12	13	14	
250	1	2	3	3	4	5	5	6	7	7	8	9	9	10	10	11	12	12	13	13	14	14	15	16	
300	2	2	3	4	5	5	6	7	8	9	10	11	12	13	13	14	15	16	16	17	18	19	20	20	
350	2	3	4	5	5	6	7	8	9	10	11	12	13	14	15	16	16	17	18	19	20	21	22	23	
400	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
450	2	4	5	6	7	8	9	10	11	12	13	14	15	16	18	19	20	21	22	24	25	26	27	28	
500	3	4	5	7	8	9	10	12	13	14	16	17	18	20	21	22	24	25	26	27	29	30	31	33	
600	3	5	6	8	9	11	13	14	16	17	19	20	22	24	25	27	28	30	31	33	35	36	38	39	
700	4	5	7	9	11	13	15	16	18	20	22	24	26	27	29	31	33	35	37	38	40	42	44	46	